




VIEW YOUR RAM SURVEY EQUIPMENT: METERS, LIQUID SCINTILLATION COUNTERS, AND GAMMA COUNTERS


[Navigate to EHSA](#) and log in with your UW NetID credentials.



- Click on “Equipment”



- If you manage multiple PIs, select the PI of interest.



- You can view either your survey meters by clicking on “Meters,” or LSCs or GCs by clicking on “General License Material”.

Serial #	Manufacturer	Model	Type	Out of Service?
<input type="text"/>				
56587	LUDLUM	16	Count Rate	<input checked="" type="checkbox"/>
22007	LUDLUM	3	Count Rate	<input type="checkbox"/>
33512	LUDLUM	18E	Count Rate	<input checked="" type="checkbox"/>
33897	LUDLUM	2	Count Rate	<input type="checkbox"/>
A279F	BICRON	RSO-5	Exposure Rate	<input type="checkbox"/>
33101	LUDLUM	3	Count Rate	<input type="checkbox"/>

Red Equipment is Over Due				
Date	History Type	Status	Results	Next Due
05-16-2017	Count Rate Calibration	Complete	Pass	05-16-2018

- Out of service meters will have a check box in the “Out of Service?” column. Out of service meters do not require calibration, even though they might appear overdue for calibration.
- You can view the last time a meter was calibrated, and when it next due for calibration.



- Press the EHSA button in the upper left corner to navigate back to the main page.